

**Picchi High Production Machining Center  
Machine Specifications and Features**

Model	Zero 2
Tool Change Time	0 (pendulum function)
Total Number of Axes	5 Axes
Spindles	2 HSK63A
Spindle HP	27 HP
ATC Magazine	30 tools (60 Optional)
CNC Control	840D Siemens